


! Please fasten the screws again if you find them were loosed after used long time.



Spare Parts List

No.	Pictures	Quantity
①		1
②		1
③		1

4mm X1

No.	Pictures	Quantity	Extra
④		1	
⑤		1	
⑥		4	1
⑦		4	1
⑧		4	1
⑨		4	1
⑩		4	1

P&W-020-S




Assembly instructions

1


1. Installing the wooden legs and connector as shown.

! There are some letters on the wooden legs and connectors. Please according the picture and keeping the assembly sequence no change. The wooden legs with letters are toward to the plastic parts.



2

2. Tightened the screws and nuts as shown.



3

3. Installing the legs part and the shell as shown.

